

2021 Ascent

1- CUSTOMER STATES PANEL IN CABINET ABOVE COUCH IS COMING UNATTACHED FROM THE BOTTOM. C/C; ADHESIVE FAILURE. REMOVE REINSTALL DOOR LATCH HARDWARE CAREFULLY PRY UP FORMICA AND WEDGE. USING STAYBOND GLUE BACK TOGETHER, CLAMP TO SECURE CLEAN UP
LABOR REQUESTING; @ 1.50 HRS **1.0 approved maximum.**