

2021 Ontour

SHOWER FAUCET IS LEAKING INTERNALLY AT HANDLE, CANNOT REPAIR, NEED TO R/R SHOWER FAUCET. Part # DF-SA150-CP \$40.00. 1.50 approved plus part cost \$40.00. You will need to remove the fridge and remove the back panel to access the shower faucet.