
PuMA measure

HSC (Hill Start Control) malfunctions

US 64465398-03 - 5/3/21

Complaint:

The hill start control operation may be sporadic.

Cause

Software issue with torque calculation.

Measure

Hill-hold faults were remedied in I level K001-18-07-521, available as of November 2018.

Please update the bike I-level to the newest version.

Validity information

| | |
|--------------------|--------------------------------|
| Model series: | [K51, K50, K53, K52, K54, K48] |
| Engine range: | [ALL] |
| Body style: | [ALL] |
| Fault codes: | [] |
| Production period: | - |

Repair overviews

61/35/023/21582, Basic module, Cannot be encoded with VFC, , Revision index old, , Program/Coding