

# SS 715-WST 2021 49X Transmission Cooler Line Plumbing Fitting

## **Applicable Vehicles**

49X vehicles built with manual or automated manual transmissions.

## **Symptoms**

Leaking transmission fluid, low fluid pressure, high fluid temperature.

## **Issue**

Transmission cooler line plumbing fitting connections at the radiator may have relative movement between rail and radiator allowing fittings to become loose and leak.


## **Solution**

Install parts below to existing trans cooler plumbing lines as shown:


TYCDCT110HIR Tie cable dual, .375 to 2.25 quantity(2)

23-12781-725 SCR-MACH,PNH HDL,LKG,M6.25 quantity(2)

07-25565-000 BAR-RETAINER,PLUMBING quantity(1)




Retainer assembly



Labels :

49X

Add tags

 0 Kudos

Comment