

SS 717-WST 2021 49X Door Drain Plug & Water Pooling

Applicable Vehicles

49X vehicles built

Symptoms

Water pooling inside of driver or passenger doors.


Issue

Drain hole location not allowing enough water to drain timely.

Solution

2 solutions for water drainage:

- Remove drain plug located at the bottom of the door shown below
- Drill 1/4" hole through center of drain plug



Labels :

49X

Add tags

1 Kudo

Comment