## On-car analysis list from August 31st, 2021 please contact VW Helpline before attempting repair

|            | Models   | MY    | Engine                     | <b>Transmission</b> | Topic                             | Customer Complaint  |
|------------|--|-------|----------------------------|---------------------|-----------------------------------|---|
| Powertrain | Atlas, Atlas Cross<br>Sport  | 20-21 | 3.6L<br>(CDVC)             | All                 | MIL-on P0087 P0148 P053F          | Customer states MIL-on with P0087 P0148 P053F in the ECM (Untouched vehicles)   |
| Chassis    | Jetta, GTI, Golf   | 21    | All                        | Manual Only         | Clutch Pedal Noise<br>(8/16/2021) | Customer states noise during clutch pedal operation (Untouched vehicles) (only looking for clutch pedal related noises) |
| Body       | Atlas, Atlas Cross<br>Sport  | 21    | All                        | All                 | Cable Disconnected                | Customer states hood release inoperative. (Untouched vehicles)  |
| Other      | Jetta, Golf, Jetta<br>SportWagen, Golf<br>SportWagen,<br>Beetle, Beetle<br>Convertible | 09-14 | 2.0 TDI<br>(CBEA and CJAA) | All                 | Gen 1 TDI                         | Customer states MIL-on with P0401 (TSB 01-18-13 2034898 must be applicable and completed before calling VW Helpline)    |