


TECHNICAL TOPICS BODY/CHASSIS



<p>Heatshield Contact With Rear Driveshaft</p>	<p>21 – 22MY Defender</p>
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> - A customer may report a grinding type noise during heavy braking. <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> - This may be caused by the rear driveshaft contacting the exhaust heat shield. <p><u>Status:</u></p> <ul style="list-style-type: none"> - Update Prior to Sale Campaign N611 UPS7621 has been published to proactively address this concern on unsold vehicles by providing instructions to modify the exhaust heat shield. - TSB JLRNA02090NAS1 is going through sign-off to address this concern on sold vehicles upon a customer complaint. 	



PRINTED COPIES ARE UNCONTROLLED