



CAMPAIGN LAUNCH STATUS

N591 – SERVICE ACTION INCORRECT 20” WHEELS INSTALLED



N591 OWNER NOTIFIED SERVICE ACTION - L462 INCORRECT 20” WHEELS INSTALLED

AFFECTED MODELS	21-22MY Discovery with 20” wheels
VOLUME AFFECTED  Aero Viper Style  Discus Style REPAIR TIME	269 USA 2 CAN Some customers have paid for the optional Aero Viper style 5011 wheel but received the standard Discus style 5122 wheel and some customers have received the optional Aero Viper style wheel at no additional cost. Customers will be notified by mail and given the option of having the wheels replaced back to the ordered spec or being reimbursed if they ordered the optional Viper style wheel but choose to keep the Discus style. Up to 1.5 hrs + drive in/out, if wheels are replaced.
TARGET CAMPAIGN LAUNCH	August 23rd, 2021
Notes	