Service Alert

Mazda North American Operations Irvine, CA 92618-2922



Subject:	
MAZDA CONNECT CLOCK SHOWS INCORRECT TIME	Service Alert No.: SA-046/21
	Last Issued : 08/10/2021

BULLETIN NOTES

This service alert supersedes the previously issued service alert(s) listed below. The changes are noted in Red text.

Previous Service Alerts:	Date(s) Issued:
SA-041/20	03/11/20
SA-031/19	07/26/19

APPLICABLE MODEL(S)/VINS

2014-2018 Mazda3

2016-2021 Mazda6

2016-2021 CX-3

2016-2020 CX-5

2016-2020 CX-9

2016-2021 MX-5

DESCRIPTION


Some customers may complain about incorrect MAZDA CONNECT clock time. This may be caused by an incorrect clock GPS Sync setting.

Clock accuracy can be improved using the following settings:

Vehicle	Setting
Equipped with in-vehicle navigation system	Clock GPS Sync ON

Page 1 of 2

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



Note: If clock GPS Sync is ON and vehicle is started with no view of the sky, clock may be inaccurate momentarily.

Page 2 of 2

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.