

---

<b>Reference</b>	SSM75429
<b>Models</b>	Defender / L663
<b>Title</b>	New Defender L663 – Roof Opening Panel - Glass Inoperative, Sunblind loss of One Touch
<b>Category</b>	Body
<b>Last modified</b>	16-Aug-2021 00:00:00
<b>Symptom</b>	102000 Window/Glass

---

**Content****Issue:**

JLR is investigating Roof Opening Panel Inoperative/Loss of One Touch closure function

**Cause:**

Loss of calibration within the Roof Opening Panel motor assembly

**Action:**

**Please complete the following steps:**

**PLEASE NOTE –**

- Replace the Roof Opening Panel Motor (LR155102) as per TOPIx section 501-17

TOPIx Diagnosis and Testing section is currently being updated, once published, this SSM will be deleted.

Thank you in advance for your assistance with this matter.

anBhdHRicnM7MjAyMS0wOC0xNiQxMT01NDoyMC44NThtaOzEzNi4yMjYyNDguOTI7