

**SSM 50047 - 2021 F-150 - 5.0L - No Crank/No Start With No PCM
Communication - Built On Or Before 09-Apr-2021**

Some 2021 F-150 vehicles equipped with a 5.0L engine and built on or before 9-Apr-2021 may exhibit a no crank/no start with no powertrain control module (PCM) communication condition if the oil life is at or less than 20%. This may be due to various parameters within the PCM. To correct the condition, follow the service procedure in Customer Satisfaction Program 21B37.

APPLICABLE VEHICLES
2021 TRUCK: FD P702N F150