

## **SSM 50064 - 2013-2021 Various Vehicles - Noise When Brakes Are Applied**

Some 2013-2021 Ford and Lincoln vehicles may exhibit noise when the brakes are applied. When diagnosing and repairing brake noise conditions, use the Workshop Manual (WSM) and the appropriate pinpoint test in section 206-00. The brake rotors should only be machined if directed by the WSM because one or more of the following conditions are present on the braking surface: scoring, excessive corrosion/rust or pitting, bluing/discoloration and/or heat spots. For additional information, refer to WSM section 206-00.

### APPLICABLE VEHICLES

2020 - 2021 CAR: TV U611N AVIATOR  
2021 TRUCK: G1 U725N BRONCO  
2021 CAR: HD CX430N C-SUV  
2017 - 2020 CAR: PL D544N CONTINENTAL  
2020 - 2021 CAR: TF CX483N CORSAIR  
2015 - 2021 CAR: DQ CD539N EDGE  
2014 - 2018 CAR: ED CD539A EDGE  
2020 - 2021 CAR: ED CD539A EDGE  
2013 - 2019 TRUCK: M2 C520N ESCAPE  
2020 - 2021 CAR: TC CX482N ESCAPE  
2018 - 2021 TRUCK: B8 U553N EXPEDITION  
2020 - 2021 CAR: TW U625N EXPLORER  
2015 - 2020 TRUCK: FC P552N F-150  
2021 TRUCK: FD P702N F150  
2017 - 2021 TRUCK: FE P558N SUPER DUTY  
2013 - 2020 CAR: C7 CD391N FUSION  
2013 - 2020 CAR: C7 CD391N FUSION  
2016 - 2021 CAR: D9 U540N MKX  
2013 - 2020 CAR: C9 CD533N MKZ  
2013 - 2020 CAR: C9 CD533N MKZ  
2015 - 2021 CAR: ZG S550N MUSTANG  
2021 CAR: GW CX727N C-EV  
2018 - 2021 TRUCK: B9 U554N NAVIGATOR  
2013 - 2019 CAR: PH D258N TAURUS