



Preliminary Information

PIT5849 Tail Lights Remain On After Passive Locking and/or Dead Battery

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado	2022	All	All	All	All
GMC	Sierra	2022	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment that the rear tail / parking lights stay on and do not time out after exiting the vehicle and passive locking the vehicle. This condition can lead to a dead battery.
Cause	The cause of this condition is a BCM Software issue.

Correction:

GM Engineering is working on a fix. Because this condition only occurs if passive locking is used please turn off passive locking in vehicle settings until a fix is released.

Additional SI Keywords

Park left right lamps lamp lighting light taillight taillamp

Version History

Version	1
Modified	07/26/2021 - Created on.



GENERAL MOTORS