



# Preliminary Information

## PIT5812B Grind Noise From Brakes

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Equinox	2021	All	All	All	All
GMC	Terrain	2021	All	All	All	All

<b>Involved Region or Country:</b>	<b>North America</b>
<b>Condition:</b>	<b>Grinding noise on brake apply cold that dissipates after a few stops.</b>
<b>Cause:</b>	<b>New no copper pad composition.</b>

Engineering is investigating this concern and working towards a resolution. Replacing pads will not eliminate this concern for the long term. Deglazing the pads and rotors does help the concern in the short term. This PI will be removed and a bulletin released when the field fix is available.

### Version History

<b>Version</b>	<b>3</b>
<b>Modified</b>	<b>02/02/2021 - Created on. 05/10/2021 - Revised to add models. 06/30/2021 - Removed Colorado and Canyon models due to the release of 21-NA-142</b>

