Toyota Motor Sales, USA, Inc. 6565 Headquarters Drive

Plano, TX 75024 (469) 292-4000

Original Publication Date: July 8, 2021

To: All Toyota Dealer Principals, General Managers, Service Managers, and Parts Managers

SPECIAL SERVICE CAMPAIGN 21TC04 (Remedy Notice)

Certain 2021 Model Year C-HR Incorrect Programming for Rear Seat Belt Reminder Indicator

Model / Years	Production Period	Approximate Total Vehicles
C-HR – 2021 Model Year	Late July 2020 – Mid-May 2021	28,820

Condition

The subject vehicles are equipped with a rear seat belt reminder system that illuminates indicators temporarily after the ignition is turned on if rear seat belts are not buckled. Due to incorrect programming in a certain electronic control unit, certain situations can cause the rear seat belt reminder system not to illuminate the indicator as designed.

Remedy

Any authorized Toyota dealer will update the combination meter system ECU software FREE OF CHARGE.

Covered Vehicles

There are approximately 28,820 vehicles covered by this Special Service Campaign. Approximately 2,136 vehicles involved in this Special Service Campaign were distributed to Puerto Rico.

Owner Letter Mailing Date

Toyota will begin to notify owners in early October, 2021. A sample of the owner notification letter has been included for your reference.

Toyota makes significant effort to obtain current customer name and address information from each state through industry resources when mailing owner letters. In the event your dealership receives a notice for a vehicle that was sold prior to the Special Service Campaign announcement, it is the dealership's responsibility to forward the owner letter to the customer who purchased the vehicle.

Please note that only owners of the covered vehicles will be notified. If you are contacted by an owner who has not yet received a notification, please *verify eligibility by confirming through TIS prior to performing repairs*. Dealers should perform the repair as outlined in the Technical Instructions found on TIS.

Dealer Inventory Procedures

New and Used Vehicles in Dealership Inventory (In-Stock Vehicles)

To ensure customer satisfaction, Toyota requests that dealers complete this Special Service Campaign on any new or used vehicles currently in dealer inventory that are covered by this Special Service Campaign prior to customer delivery. However, if the campaign cannot be completed (for example, due to remedy parts availability), delivery of a covered vehicle is acceptable if disclosed to the customer that the vehicle is involved in a Special Service Campaign.

Toyota expects dealers to use the attached Customer Contact and Vehicle Disclosure Form to obtain vehicle buyer information. Dealers are expected to provide a copy of the completed form, along with the most current FAQ, to the vehicle buyer. Toyota and the dealer may use this information to contact the customer when the remedy becomes available.

Keep the completed form on file at the dealership and send a copy to quality_compliance@toyota.com. In the subject line of the email state "Disclosure Form 21TC04" and include the VIN.

NOTE: Dealers can identify if any of their new and used inventory has any open campaigns in the Vehicle Inventory Summary available in Dealer Daily (**Non SET and GST dealers:** https://dealerdaily.toyota.com/). The Vehicle Inventory Summary may take up to 4 hours to populate information for newly launched campaigns.

Toyota Certified Used Vehicle (TCUV)

The TCUV policy prohibits the certification of any vehicle with an outstanding Safety Recall, Special Service Campaign, or Limited Service Campaign. Thus, no affected units are to be designated, sold, or delivered as a TCUV until all applicable Safety Recalls, Special Service Campaigns, and Limited Service Campaigns have been completed on that vehicle.

Customer Handling, Parts Ordering, and Remedy Procedures

Customer Contacts

Customers who receive the owner letter may contact your dealership with questions regarding the letter and/or the Special Service Campaign. Please welcome them to your dealership and answer any questions that they may have. A Q&A is provided to assure a consistent message is communicated.

Customers with additional questions or concerns are asked to please contact the Toyota Brand Engagement Center (1-888-270-9371) - Monday through Friday, 8:00 am to 8:00 pm, Saturday 9:00 am to 7:00 pm Eastern Time.

Head Unit Notifications

Head unit notifications are electronic messages that are displayed in the vehicle's audio system screen. Customers who receive head unit notification regarding this Special Service Campaign are requested to schedule an appointment with their authorized dealer to have this Special Service Campaign completed.

When these messages are received by the vehicle's Data Communication Module, the head unit will display a pop-up prompt stating that the vehicle has a new Special Service Campaign. The prompt will contain options to 'Remind Me' or to 'View' the message. If a customer chooses 'Remind Me', the customer can then choose to be reminded again on next trip, in 7 days, or in 30 days. If a customer views and then closes the message, the message will be available in the Notification App if the customer chooses to review it again. If the vehicle's completion status remains incomplete for a period of 90 days from the message being viewed, the head unit may display a renotification pop-up prompt as an additional reminder to the customer to have this Special Service Campaign completed.

The message will completely clear from the vehicle once the following conditions are met: The Special Service Campaign is completed, the dealer has filed a claim, and the claim is approved by Toyota. Then the message will be cleared at the next clearing cycle, which currently happens daily.

Owners who receive a head unit notification after having this Special Service Campaign completed can be advised to ignore the message. Owners with additional concerns can be directed to the Toyota Brand Engagement Center (1-888-270-9371) - Monday through Friday, 8:00 am to 8:00 pm, Saturday 9:00 am to 7:00 pm Eastern Time.

Salvage Title Vehicles

Every attempt should be made to complete an open Special Service Campaign when circumstances permit, unless noted otherwise in the SSC dealer letter.

For complete details on this policy, refer to Toyota Warranty Policy <u>4.17</u>, "What Is Not Covered by The Toyota New Vehicle Limited Warranty".

Media Contacts

It is imperative that all media contacts (local and national) receive a consistent message. In this regard, all media contacts must be directed to Ed Hellwig (859) 815-9968 in Toyota Corporate Communications. Please do not provide this number to customers. Please provide this contact only to media.

Technician Training Requirements

The repair quality of covered vehicles is extremely important to Toyota. All dealership technicians performing this repair are required to successfully complete the most current version of the E-Learning course "Safety Recall and Service Campaign Essentials". To ensure that all vehicles have the repair performed correctly; technicians performing this recall repair are required to currently have completed all of the following courses:

T623 - Toyota Electrical Circuit Diagnosis

It is the dealership's responsibility to select technicians with the above certification level or greater to perform this recall repair. Carefully review your resources, the technician skill level, and ability before assigning technicians to this repair. It is important to consider technician days off and vacation schedules to ensure there are properly trained technicians available to perform this repair at all times.

Remedy Procedures

Refer to TIS for Technical Instructions on repair. Conduct all non-completed Safety Recalls and Service Campaigns on the vehicle during the time of appointment.

Repair Quality Confirmation

The repair quality of covered vehicles is extremely important to Toyota. To help ensure that all vehicles have the repair performed correctly, please designate at least one associate (someone other than the individual who performed the repair) to verify the repair quality of every vehicle prior to customer delivery.

Parts Recovery Procedures

All parts replaced as part of this Special Service Campaign must be turned over to the parts department until appropriate disposition is determined. The parts department must retain these parts until notification via the Parts Recovery System (PRS) is received indicating whether to ship or scrap the parts. These parts are utilized by various departments for defect analysis, quality control analysis, product evaluation, as well as other purposes.


To help minimize dealer storage challenges, Toyota recommends that dealers:

- File the campaign claim accurately and promptly. The time a dealer is required to hold parts is based on when the campaign claim is paid by Toyota.
- Monitor the Warranty Parts Recovery Notifications and Part Scrap Report regularly.

Refer to Warranty Policies 9.3 and 9.6 for additional details.

Warranty Reimbursement Procedures

Warranty Reimbursement Procedure




Op Code	Description	Flat Rate Hours
AHTC41	Reprogram – Combination Meter System ECU	0.8

- The flat rate times include 0.1 hours for administrative cost per unit for the dealership.
- In the rare case that the Combination Meter System ECU contains the latest calibration ID (no software update needed), use opcode AHTC41.

Claim Filing Accuracy and Correction Requests

It is the dealer's responsibility to file claims correctly for this Special Service Campaign. This claim filing information is used by Toyota for various government reporting activities; therefore, claim filing accuracy is crucial. If it has been identified that a claim has been filed using an incorrect Op Code or a claim has been filed for an incorrect VIN, refer to Warranty Procedure Bulletin PRO17-03 to correct the claim.

Campaign Designation / Phase Decoder



Please review this entire package with your Service and Parts staff to familiarize them with the proper step-by-step procedures required to implement this Special Service Campaign.

Thank you for your cooperation. TOYOTA MOTOR SALES, U.S.A., INC.



SPECIAL SERVICE CAMPAIGN 21TC04 (Remedy Notice)

Certain 2021 Model Year C-HR Incorrect Programming for Rear Seat Belt Reminder Indicator

Frequently Asked Questions
Original Publication Date: July 8, 2021

Q1: What is the condition?

A1: The subject vehicles are equipped with a rear seat belt reminder system that illuminates indicators temporarily after the ignition is turned on if rear seat belts are not buckled. Due to incorrect programming in a certain electronic control unit, certain situations can cause the rear seat belt reminder system not to illuminate the indicator as designed.

Q1a: Does this condition impact rear seat belt performance?

A1a: The performance of the rear seat belts is not affected by this condition.

Q2: What is Toyota going to do?

A2: Toyota will send an owner notification by first class mail starting in early October, 2021, advising owners to make an appointment with their authorized Toyota dealer to have the software (in combination meter system ECU) updated **FREE OF CHARGE**.

Q3: Which and how many vehicles are covered by this Special Service Campaign?

A3: There are approximately 28,820 vehicles covered by this Special Service Campaign.

Model Name	Model Year	Production Period
C-HR	2021	Late July 2020 – Mid-May 2021

Q3a: Are there any other Lexus/Toyota/Scion vehicles covered by this Special Service Campaign in the U.S.?

A3a: No, there are no other Lexus/Toyota/Scion vehicles covered by this Special Service Campaign.

Q4: How long will the repair take?

A4: The repair takes approximately one hour. However, depending upon the dealer's work schedule, it may be necessary to make the vehicle available for a longer period of time.

Q5: How does Toyota obtain my mailing information?

A5: Toyota uses an industry provider who works with each state's Department of Motor Vehicles (DMV) to receive registration or title information, based upon the DMV records. Please make sure your registration or title information is correct.

Q6: What if I have additional questions or concerns?

A6: If you have additional questions or concerns, please contact the Toyota Brand Engagement Center at 1-888-270-9371 Monday through Friday, 8:00 am to 8:00 pm, Saturday 9:00 am to 7:00 pm Eastern Time.

Certain 2021 Model Year C-HR Incorrect Programming for Rear Seat Belt Reminder Indicator Special Service Campaign 21TC04 (Remedy Notice)

[VIN]

Dear Toyota Customer:

At Toyota, we are dedicated to providing vehicles of outstanding quality and value. As part of our continuing efforts to provide superior customer satisfaction, Toyota is announcing a Special Service Campaign, which includes your vehicle.

You received this notice because our records, which are based primarily on state registration and title data, indicate that you are the current owner.

What is the condition?

The subject vehicles are equipped with a rear seat belt reminder system that illuminates indicators temporarily after the ignition is turned on if rear seat belts are not buckled. Due to incorrect programming in a certain electronic control unit, certain situations can cause the rear seat belt reminder system not to illuminate the indicator as designed.

What will Toyota do?

Any authorized Toyota dealer will update the combination meter system ECU software FREE OF CHARGE.

What should you do?

Before you are inconvenienced by this condition, any authorized Toyota dealer will perform the software update **FREE OF CHARGE** to you.

Please contact your authorized Toyota dealer to make an appointment to have the combination meter system ECU software update performed. The remedy will take approximately one hour. However, depending on the dealer's work schedule, it may be necessary to make your vehicle available for a longer period of time.

What if you have other questions?

- Your local Toyota dealer will be more than happy to answer any of your questions.
- For more information on this and other campaigns, please visit www.toyota/lexus.com/recall.
- ✓ If you require further assistance, you may contact the Toyota Customer Experience Center at 1-888-270-9371 Monday through Friday, 8:00 am to 8:00 pm, Saturday 9:00 am to 7:00 pm Eastern Time.

If you would like to update your vehicle ownership or contact information, please visit https://www.toyota.com/recall/update-info-toyota. You will need your full 17-digit Vehicle Identification Number (VIN) to input the new information.

If you are a vehicle lessor, please assist us by forwarding this notice to the lessee.

We have sent this notice in the interest of your continued satisfaction with our products, and we sincerely regret any inconvenience this condition may have caused you.

Thank you for driving a Toyota.

Sincerely,

TOYOTA MOTOR SALES, U.S.A., INC.



Toyota Motor Sales, USA, Inc. 6565 Headquarters Drive Plano, TX 75024 (469) 292-4000

CUSTOMER CONTACT & VEHICLE DISCLOSURE FORM

This form is not applicable for TCUV units.

This form is not applicable for reov at		
	hat the vehicle will need to be retu	remedy parts are not available, and the remedy has NO 1 irned to an authorized Toyota dealer to have the remedy
Customer Signature		
•	-	munity at http://www.toyota.com/owners/ and regularly fercar.gov. You will need to input your 17-digit Vehicles
VIN		Campaign Code
Model	Model Year	
Customer Information		
Customer Name		Customer Email
Customer Address		Home Phone #
		Mobile Phone #
		Date
information will only be used		n notify you when the remedy becomes available. This ou'd like to update your preferred contact information at 1-888-270-9371.
Dealer Information		
Dealer Name/Address		Dealer Code
		Dealer Phone Number
		Dealer Staff Name

Dealer Staff Signature