

# **Technical Service Bulletin**

#### 91 Audi connect GEN3: MY21 A8/S8 No Services in MMI and SOS LED does not turn green after PDI

91 21 25 2064386/1 September 1, 2021.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8, S8	2021	All	Not Applicable

### Condition

One or all of the following conditions exist:

- The vehicle is a MY2021 A8 or S8.
- Audi connect services do not function.
- SOS LED is off or flashes red.

### **Technical Background**

A technical configuration issue exists in the Audi connect backend that only affects late-built MY21 A8 & S8 models built around CW25/21 and later.

#### **Production Solution**

A customer service solution is being developed and does not affect new vehicle production.

#### Service

If after performing the PDI Total process the SOS flashes red and does not transition to a solid green light, then please open a <u>web ticket</u> with the Audi connect Technical Support Team: https://audi.zendesk.com/.



You will need to use a dealer email address to register for access to the web ticketing system. Using a personal Gmail or Yahoo account will not allow you to register to the site. If this is not possible, then please contact us at connect.support@audi.com so we can verify your dealer credentials and then allow you to utilize your personal email to access the web ticketing system.

© 2021 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



# **Technical Service Bulletin**

#### Warranty

This TSB is informational only and not applicable to any Audi Warranty. This procedure is a necessary part of the vehicle PDI.

## **Additional Information**

All part and service references provided in this TSB (2064386) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

© 2021 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.