

SSM 50139 - 2020-2021 Transit - Factory Keyless Entry - Broken Flip Key

Some 2020-2021 Transit vehicles equipped with factory keyless entry remote may exhibit a broken flip-key at the base of the fob. A broken key can be replaced with the current service part, which is a like-for-like replacement. However, for customers that may require a more robust key due to high key cycle activity, a mechanical key (Rotunda part numbers: pre-cut 164-R8290, uncut 164-R8289) can be programmed to the vehicle and used in conjunction with the original fob that has the broken flip-key for the remote keyless entry functions. To program the keys, refer to Workshop Manual (WSM), Section 419-01B.

APPLICABLE VEHICLES

2020 - 2021 TRUCK: TH V363N TRANSIT