



## **Model Year 2016, 2017 Chassis Equipped With A Fuller 10 Speed Transmission Displaying Error Message " Neutral Not Secured " While Attempting A Parked Regeneration Or NOx Conversion Test**



> **Internal Content**

Advise to Update or Reload the Engine ECU software on the truck if the truck with this problem is listed below. If the truck is not a truck listed below and has the same failure mode, please contact Technical Support Services for additional guidance.

Affected Fuller Manual 10-Speed Variants:

F14810B  
F14810BM  
F14810C  
F15810CM  
F15810B  
F15810BM  
F15810C  
F16810CM  
F16810C

Affected Current Known Vehicles:  
Model Year 2016:  
N-180868 to N-180892 (25 Trucks)

Model Year 2017:  
N-977965  
N-977969  
N-977971  
M744-81273  
M744-81275  
M744-81274  
M744-81277  
M744-81276  
M744-81281  
M744-81279  
M744-81278  
M744-81280  
M744-81282  
N-982270

Live UI 68

N-982269

N-982271

N-982274

N-982273

N-982272



Tags

[k13902510](#)

[mid 140 instrument cluster](#)

### Related links and attachments

No links or attachments available



### Feedback

[Give feedback](#)

to help improve the content of this article