



Volvo Chassis - Volvo Dynamic Steering - Diagnostic Trouble Codes - Electronic Control Unit, Event Information



Vehicles equipped with the Volvo Dynamic Steeringsystem may exhibit DTC U300068. This communication fault will prevent the Volvo Dynamic Steering system from powering up when the vehicle is started. This fault appears only at start up.

NOTE: The vehicle is still operable if the Volvo Dynamic Steering system does not power on.

Front Active Steering (FAS)	U300094: Electronic control unit, Unexpected Operation	Inactive	13
Front Active Steering (FAS)	U300068: Electronic control unit, Event Information	Active	13
Front Active Steering (FAS)	U300049: Electronic control unit, Internal Electronic Failure	Inactive	12

At this time it has been found that this fault can be reset by performing a power cycle. **DO NOT replace the Volvo Dynamic Steering system motor.**

Create a Tech Support eService case and include any details related to faults, system issues, etc.

Please add **Attention James Olsen** in the complaint as this will aid in the gathering of documentation and information to assist engineering in their research.

[u300094](#)

[u300049](#)

[volvo dynamic steering](#)

Related links and attachments

No links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article