

# VOLVO TRUCKS DEALER BULLETIN



---

**To:** General Managers, Service Managers, Service Technicians, Warranty Managers  
**From:** Volvo Trucks – Service  
**Date:** September 30, 2021  
**Subject:** Service Literature Published and Released in September, 2021  
**Bulletin:** SLV21-009

---

The following summarizes the service literature that has been published and/or revised for the month.

## SERVICE NEWS

| BULLETIN # | TITLE       | COMMENTS |
|------------|-------------|----------|
|            | None Issued |          |

## TOOL BULLETIN

| BULLETIN # | TITLE       | COMMENTS |
|------------|-------------|----------|
|            | None Issued |          |

## FIELD SERVICE BULLETIN

| BULLETIN # | TITLE       | COMMENTS |
|------------|-------------|----------|
|            | None Issued |          |
|            |             |          |

## SERVICE PROGRAM

| BULLETIN # | TITLE                                  | COMMENTS |
|------------|----------------------------------------|----------|
| S7605      | Transmission Mounting Bolts Inspection | New      |
| S7598      | Inlet Valve Spring Replacement         | New      |

## RECALLS

| BULLETIN # | TITLE       | COMMENTS |
|------------|-------------|----------|
|            | None Issued |          |

# VOLVO TRUCKS DEALER BULLETIN



## CASE BASED REASONING (CBR)

### NEW SOLUTIONS

| SOLUTION # | TITLE                                                                                                          |
|------------|----------------------------------------------------------------------------------------------------------------|
| CBR-2107   | Reductant Tank Temperature Sensor Troubleshooting Guide (UQLS) - US17 Emissions And Newer                      |
| CBR-2153   | Volvo Chassis - Volvo Dynamic Steering - Diagnostic Trouble Codes - Electronic Control Unit, Event Information |
| CBR-2149   | Particulate Matter (PM) Sensor Troubleshooting Guide - US14+OBD16 And Newer Emissions                          |
| CBR-2151   | Leese Neville Alternator Stud Cable Arrangement                                                                |
| CBR-2134   | Volvo VN Models - Overhead Light Loose, Detaching From Headliner                                               |
| CBR-2136   | Volvo Chassis - Model VN - Water Intrusion In Back Of Cab, Back Wall Of Bunk Leaking                           |

### UPDATED SOLUTIONS

| SOLUTION | TITLE                                                                                                                                                                                     | COMMENTS                                                                                |
|----------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|
| CBR-328  | Diagnostic Trouble Codes (DTC) P208064, P208464, P242B64 and P246F64 Lighting The Malfunction Indicator Lamp (MIL) - US17+OBD19 And Newer Emissions, Model Years 2020 and Newer           | Updated with new images including T4 exhaust temp sensor.                               |
| CBR-2106 | Volvo Chassis - Unable To Program VECU: Error Code 155; Possible EMS DTC U000188 CAN Communication Backbone 2 Net - VECU5 Only                                                            | Updated tagging for improved searchability.                                             |
| CBR-2    | Updated PM Sensor Removal Procedure - US17+OBD16 and Newer Emissions                                                                                                                      | Added Link to Bung Replacement FSB 258-039 – Removed statement about replacement of SCR |
| CBR-2116 | NOx Sensor Replacement Guide - US10+OBD13 And Newer Emissions                                                                                                                             | Updated the solution to point tech towards our new NOx Replacement CBR 2116             |
| CBR-949  | Diagnostic Trouble Code (DTC) P229F-64; Diagnostic Information - US10+OBD2013 Emissions And Newer                                                                                         | Expired - Newer diagnostic information available.                                       |
| CBR-992  | Model Year 2016, 2017 Chassis Equipped With A Fuller 10 Speed Transmission Displaying Error Message " Neutral Not Secured " While Attempting A Parked Regeneration Or NOx Conversion Test | Expired - Information outdated.                                                         |
| CBR-409  | Issue With The Particulate Matter ( PM ) Sensor Monitoring Test ( 2589 - 08 - 03 - 17 ) With A Manual Transmission                                                                        | Expired - Operation corrected in PTT.                                                   |
| CBR-493  | Volvo Chassis - Equipped With A D16J Engine - Premium Tech Tool ( PTT ) Error Code 38 Displayed During A Regen                                                                            | Expired - Operation corrected in PTT.                                                   |
| CBR-949  | Diagnostic Trouble Code (DTC) P229F-64; Diagnostic Information - US10+OBD2013 Emissions And Newer                                                                                         | Expired - Newer diagnostic information available.                                       |
| CBR-420  | Model Year 2017, 2018 - US17 GHG Engines-Unused Port On Exhaust Pipe For One Box System Installations                                                                                     | Updated tagging for improved searchability.                                             |
| CBR-411  | Volvo Chassis - Field Service Bulletin - FSB 293-027 EGR Mass Flow Rate Low - (SPN 2659 FMI 18 Or P0401)                                                                                  | Expired - Information outdated.                                                         |