

01SLG2021-09-08

Product Line: SLG

Post Date: 2021-09-08

MSD Thread Subject

Slingshot ATM odd shifting/ harsh shifting, or shifting at wrong RPM

MSD Post Content

A call we get sometimes at Polaris Technical Service is the reported odd shifting characteristics of a Slingshot with auto drive transmission. Before calling us or starting a case looking for help; make sure the wheel & tire sizes have not been changed from production size.. If they have, please put stock wheels and tires on and test drive to see if that addresses the problem before contacting tech line. The load points in the calibration are all based off of the values for the wheel sizes used during development and validation. If aftermarket wheels & tires of a different size are fitted this has proven to cause abnormal shift patterns in several instances. Please make customers aware of this if they plan to customize their Slingshot. Hope this helps -Bob