
Reference	SSM75429
Models	Defender / L663
Title	New Defender L663 – Roof Opening Panel - Glass Inoperative, Sunblind loss of One Touch
Category	Body
Last modified	06-Sep-2021 00:00:00
Symptom	102000 Window/Glass
Attachments	Blind Motor Clip.pdf (Blind Motor Clip.pdf)

Content**Issue:**

JLR is investigating Roof Opening Panel Inoperative/Loss of One Touch closure function

Cause:

Loss of calibration within the Roof Opening Panel Blind motor assembly

Action:

Please complete the following steps:

PLEASE NOTE –

- Replace the Roof Opening Panel Blind Motor (LR155102) as per TOPIX section 501-17
- Please ensure the clip is transferred over from the old motor to the new motor (See attachment)

TOPIX Diagnosis and Testing section is currently being updated, once published, this SSM will be deleted.

Thank you in advance for your assistance with this matter.

anBhdHRicnM7MjAyMS0wOS0wN1QxMjoxOT01MC43OTFaOzY5LjEyNC4yMjYuMTE3Ow==