

---

<b>Reference</b>	SSM75463
<b>Models</b>	Defender / L663 Discovery / L462 Range Rover / L405 Range Rover Sport / L494 Range Rover Velar / L560
<b>Title</b>	XCL AJ20-P6 thermostat MIL for DTC P0128-00.
<b>Category</b>	Engine
<b>Last modified</b>	09-Sep-2021 00:00:00
<b>Symptom</b>	499000 Basic Engine

---

**Content** Issue:

Customer sees engine warning light, initiated by DTC P0128-00.

This DTC is indicating a thermostat range performance issue and is flagged due to hardware fault with the thermostat assembly related to an internal degas valve.

Cause:

Supplier part quality issue.

Action:

If DTC P0128-00 is flagged on AJ20-P6 engine vehicles, please replace the thermostat assembly as per Topix and clear the DTC. Ensure the vehicle coolant level is topped up and test drive.

J6P3-8575-AC / LR121420 (LandRover)

A software update is not required to resolve this issue.

Thank you for your assistance with this matter.

anBhdHRicn7MjAyMS0wOS0xM1QxMjpwND00NC44NDBaOzEzNi4yMjYyNDguODE7