

Document Information

Location: Electrical & Interior

Topic: Centre storage lid not opening

Condition: Intermittent

Diagnostic Trouble Codes: N/A

Measure

In the event that the centre console storage lid does not open when the button is pressed, proceed to replace the locking actuator, ensuring there is no damage to the mounting bracket.

It is also imperative to update the software to PF4.4 in order to ensure there is no repeat of this issue once repaired.

Parts Information

N/A

Attachments

N/A

KA Update Information

N/A