

**On-car analysis list from October 13th, 2021**  
**please contact VW Helpline before attempting repair**

	Models	MY	Engine	Transmission	Topic	Customer Complaint
<b>Powertrain</b>	Atlas, Atlas Cross Sport	20-21	3.6L (CDVC)	All	MIL-on P0087 P0148 P053F	Customer states MIL-on with P0087 P0148 P053F in the ECM <b>(Untouched vehicles)</b>
<b>Chassis</b>	Atlas, Atlas Cross Sport	21	All	All	Front Suspension Noise	Customer states noise from front suspension <b>(Untouched vehicles)</b> <b>Must be after VIN break MC537933 (Atlas) or MC201092 (Atlas Cross Sport)</b>
	Jetta, GTI, Golf	21	All	Manual Only	Clutch Pedal Noise	Customer states noise during clutch pedal operation <b>(Untouched vehicles)</b> <b>(only looking for clutch pedal related noises)</b>
<b>Electric</b>	Jetta, Tiguan, Taos	21-22	All	All	Vehicle Doors	Customer concern of vehicle door hard to close/out of adjustment <b>(Untouched vehicles)</b>
	Atlas, Atlas Cross Sport	21-22	All	All	Airbag Light	Customer states airbag light on <b>(Untouched vehicles)</b> <b>(Must contain B100B1B and/or B100A1B in the airbag module)</b> <b>(Vehicles produced after 12/10/2020)</b>
	Passat	19-21	All	All	ODIS Communication	Customer states no crank/no start. Vehicle is towed in. <b>(Untouched vehicles)</b>
<b>Body</b>	Atlas, Atlas Cross Sport	20-21	All	All	HVAC Temperature flap	Customer states there is a popping/clicking noise while operating temperature settings
<b>Other</b>	Jetta, Golf, Jetta SportWagen, Golf SportWagen, Beetle, Beetle Convertible	09-14	2.0 TDI (CBEA and CJAA)	All	Gen 1 TDI	Customer states MIL-on with P0401 <b>(TSB 01-18-13 2034898 must be applicable and completed before calling VW Helpline)</b> <b>(Must be a repeat DPF failure case)</b>