



Technical Journal

TITLE:

AC evaporator repair, additional parts needed

REF NO:
TJ 35912.3.1

ISSUING DEPARTMENT:
Technical Service

CAR MARKET:
United States and Canada

PARTNER:
3 US 7510 Volvo Car USA

ISSUE DATE:
2021-06-04

STATUS DATE:
2021-06-07

FUNC GROUP:
8720

FUNC DESC:
Air distribution

Page 1 of 4

“Right first time in Time”

Attachment

File Name	File Size
TJ 35912 1.PNG	1.3298 MB
TJ 35912 2.PNG	0.0476 MB

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

* Updated Description.

*This TJ applies for non PHEV.

If the AC evaporator needs to be replaced, please follow advice under “Service”.

CSC Customer Symptom Codes

Code	Description
KI	Temperature control/A/C not cold enough
TB	Temperature control/A/C does not work



Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2019-2019		-	201835-201848
225							2019-2019		-	201817-201848
227							2019-2019		-	201846-201848
234							2017-2017		-	201617-201848
235							2017-2019		-	201624-201848
236							2017-2019		-	201646-201848
238							2018-2019		-	201646-201848
246							2018-2019		-	201717-201848
256							2016-2019		-	201505-201848

SERVICE:

When replacing the AC evaporator according to VST OP Number: 87402-2, also install Resistor (in-line jumper cable) P/N 32241228 (see picture 2) according to the method with VCC ID VCC-517278-1.

Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data:

VST OP Number:87402-2

VST Operation Number

VST Operation Number	Description
87402-2	Evaporator replace

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8720.

To view TJ attachments continue to next page. This TJ has two attachments.



TJ 35912

