

# **Technical Journal**

#### TITLE:

# Outer rear view mirror glass incorrect position after reversing

REF NO: TJ 35507.6.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada			
3 US 7	PARTNER: 7510 Volvo Car USA	ISSUE DATE: 2021-07-02	STATUS DATE: 2021-07-21		
FUNC GROUP: 8461	FUNC DESC: Manual outside mirrors, compl	Page	1 of 2		

"Right first time in Time"

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

#### **DESCRIPTION:**

If vehicle shows symptom of outer rear view mirror glass not returning to correct position after reversing, follow advice under service.

## **CSC** Customer Symptom Codes

Code	Description
SM	Door mirrors/Electrical adjustment does not work
TG	Door mirrors/Automatic adjustment (memory) does not work

#### **DTC** Diagnostic Trouble Codes

#### **Vehicle Type**

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2019-2022		0000001-0123139	201835-202124
225							2019-2022		0000001-0467820	201817-202124
227							2019-2022		0000001-0085844	201846-202124
235							2018-2022		0035090-0175464	201717-202124
236							2018-2022		0013029-0144569	201717-202124

<sup>\*</sup> Chassi break updated.

# **Technical Journal 35507.6.0**



Type	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
238						2018-2022		0015068-0245032	201717-202124
246						2018-2022		0000001-0899090	201717-202124
256						2018-2022		0190087-0799743	201717-202124
536						2019-2022		0000001-0640048	201746-202124

#### **SERVICE:**

Perform a total software upgrade according to TJ 31543.

#### Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data: VST OP number: 36004-2

## **VST** Operation Number

<b>VST Operation Number</b>	Description					
36004-2	Software control module downloading					

#### **VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8461.

Page 2 of 2 2021-07-21