



# Spartan Fire, LLC

Campaign Service Bulletin  
CSB21-350-001

**DATE:** 9/7/2021

**APPLIES TO:** This service bulletin applies to 2017 through 2021 model year, Gladiator and Metro Star model emergency response chassis cabs built between December 5, 2016 to April 5, 2021.

**CONDITION:** Rear Neway ADZ-127 suspension label has incorrect weight rating

**CORRECTION:** Replace incorrect 24,000 lb labels with 27,000 lb labels.

**LABOR ALLOCATION:** 0.5 hour

**CLASSIFICATION:** V3

**PARTS NEEDED:**

**Rear Drum Brake: Suspension part number: 3441-DD4-001**

| <u>QTY</u> | <u>Part Number</u> | <u>Description</u>         |
|------------|--------------------|----------------------------|
| 1          | 33100421           | 27,000 lb suspension label |

**Rear Disc Brake: Suspension part number 3491-DD4-001**

| <u>QTY</u> | <u>Part Number</u> | <u>Description</u>         |
|------------|--------------------|----------------------------|
| 1          | 33100426           | 27,000 lb suspension label |

**GENERAL INSTRUCTIONS:**


Thoroughly review entire service bulletin before starting work. If there are questions or concerns with steps defined in this service bulletin, contact Spartan Fire, LLC. Customer & Product Support Group.

All applicable industry safety standards must be followed when performing work identified in this procedure.

Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of specific nature in conjunction with industry standards. Professional Technicians should be appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.

## STEP-BY-STEP INSTRUCTIONS:

1. Locate suspension label on rear suspension lower control arm. *See Figure 2.1*



**FIG. 2.1**

2. Examine label capacity on original label.
  - a. If capacity indicates 27,000 lbs, no further action is needed. The label is correct.
  - b. If capacity indicates 24,000 lbs as shown in figure 2.1, then proceed to step 3.
3. Identify if original label contains a part number 33100421 or 33100426
4. Select the new label with the same part number as the original label.
5. Remove original label from control arm and dispose of properly.
6. Clean area with a wax and grease remover to ensure proper adhesion of the new correct label.
7. Remove adhesive backing from new label and carefully apply to the clean region, pressing firmly to ensure proper adhesion.

Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of specific nature in conjunction with industry standards. Professional Technicians should be appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.