

## SRS DTC U3000-49 Internal Failure of the SRS Unit

### AFFECTED VEHICLES

Year	Model	Trim Level
2020	Accord	ALL
2020	Civic	ALL
2020	Clarity	ALL
2020	CRV	ALL
2020	Fit	ALL
2020	HRV	ALL
2020	Insight	ALL
2020	Odyssey	ALL
2020	Passport	ALL
2020	Pilot	ALL
2020	Ridgeline	ALL

There are several possible causes for the SRS DTC U3000-49 (Internal Failure of the SRS Unit) to be stored. If you can duplicate the DTC, the troubleshooting will take you through the step-by-step process in isolating the faulty component. In most situations, the SRS Unit should be last on the list of components to replace. Here is a quick tip for troubleshooting a faulty seat weight sensor.

Disconnect all seat weight sensors and clear DTCs. If the DTC does not reappear then replace seat frame/rail.

NOTE: If you are not fully replacing the seat frame and are using a known good one, always find a vehicle with the same trim level. Swapping seat frames with different trim levels may result in the same DTC condition and cause confusion.