

Technical Service Bulletin

90 Instrument cluster: various malfunction LEDs are lit sporadically without DTCs

90 21 17 2064789/1 October 13, 2021.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
S4, S5	2020 - 2021	All	Analog cluster

Condition

Customer states:

- · Various malfunction indicator LEDs are sporadically lit in the instrument cluster while driving.
- The instrument cluster functions normally otherwise.

Workshop findings:

• No relevant DTCs are stored in the vehicle.

Technical Background

There is a hardware defect within the instrument cluster.

Production Solution

Not applicable.

Service

- 1. Please take photos of the customer's concern and upload them into DOC-IT with the repair order. Photos should:
 - Have a date stamp and VIN reference.
 - · Be taken in focus and with sufficient light.
- 2. Please replace the instrument cluster according to the instructions in the Elsa Repair Manual.



Technical Service Bulletin

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles.			
	G10 for CPO Covered Vehicles – Verify Owner.			
If the vehicle is outside any warranty only.		nis Technical Service Bulletin is informational		
Service Number:	9025			
Damage Code:	0040			
Labor Operations:	Replace the instrument cluster	9025 5500	See SRT with associated operations	
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 30 TU)	
	Road test prior to the service procedure	No allowance	0 TU	
	Road test after the service procedure	No allowance	0 TU	
Claim Comment:	laim Comment: As per TSB #2064789/1			

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2064789) are subject to change and/or removal.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.