

# Technical Service Bulletin

PSS 91 MIB3: favorites, home address, and stored destinations are lost

91 21 42 2062266/3 October 13, 2021. Supersedes Technical Service Bulletin Group 91 number 21-17 dated August 2, 2021 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, S4, A4 allroad, A5, A5 Cabriolet, A5 sportback, S5, S5 Cabriolet, and S5 sportback	2020 - 2022	All	MIB3
A6, A6 allroad, A6 Avant, S6, RS 6 Avant, A7, S7, RS 7, A8, S8, Q5, SQ5, Q7, SQ7, Q8, SQ8, RS Q8, RS 5, RS 5 Cabriolet, RS 5 sportback, Audi e-tron quattro, and Audi e-tron sportback	2021 - 2022	All	MIB3
A3, S3, Audi e-tron GT, and Audi RS e-tron GT	2022	All	MIB3

### **Condition**

REVISION HISTORY				
Revision	Date	Purpose		
3	-	Revised header (Added Models and Model Years) Revised Service (Updated expected release date)		
2	08/02/2021	Revised Service (Updated expected release date)		



## Technical Service Bulletin

1	02/17/2021	Initial publication

#### **Customer states:**

Last destinations, favorites, and home/work addresses are sporadically lost.

#### Workshop findings:

The concern might not be reproducible at the dealership due to it happening sporadically.

### **Technical Background**

A software bug can cause some user data to be lost on boot-up.

#### **Production Solution**

This bulletin will be updated when more information is available. A solution is currently under development.

#### **Service**

- 1. Explain to the customer that a solution is forthcoming for the 3rd quarter of 2022 and that no repairs are necessary at this point. A workaround procedure will become available by the end of 2021, by which time this PSS will be updated with that procedure.
  - Do not replace any components for this condition since this will not resolve the customer's concern.
- 2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links* >> Service), or through the Technical Assistance page in Elsa.

## **Warranty**

This TSB is informational only and not applicable to any Audi Warranty.

#### **Additional Information**

All part and service references provided in this TSB (2062266) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes



## Technical Service Bulletin

at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.