



TECHNICAL SERVICE BULLETIN

Whistle From Front Hood Area - Built On Or Before 06-Aug-2021

21-2345
08 October 2021

Model:

Ford 2021 Bronco

Issue: Some 2021 Bronco vehicles equipped with the Big Bend or Outer Banks trim levels built on or before 06-Aug-2021 may exhibit a whistle noise originating from the front of the hood area when traveling at speeds above 30 mph (50 km/h). If the whistle noise can be eliminated by taping off the gap between the hood and grille opening, this condition may be due to the hood seal design. To correct this condition, replace the hood seal with the improved hood seal.

Action: Follow the Service Procedure to correct the condition on vehicles that meet all of the following criteria:

- 2021 Bronco
- Big Bend or Outer Banks trim level
- Built on or before 06-Aug-2021
- Whistle noise originating from the front of the vehicle between the hood and grille opening

Parts

Service Part Number	Quantity	Description
M2DZ-16B990-B	1	Front Hood Seal

Warranty Status: Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Service Part Warranty (SPW)/Special Service Part (SSP)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/SPW/SSP/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2021 Bronco Big Bend/Outer Banks: Replace The Hood Seal (Do Not Use With Any Other Labor Operations)	212345A	0.3 Hrs.

Repair/Claim Coding

Causal Part:	16B990
Condition Code:	42

Service Procedure

1. Replace the existing hood seal with the improved hood seal.

© 2021 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.