

SS 704-WST2021 49X ECP (Electronic Controlled Pneumatics) Ground Noise/False Codes

Applicable Vehicles

49X vehicles

Symptoms

Audible chirping noise through speakers, leaking air through ECP, continual error codes with no problem found.

Issue

Internal board of ECP supplied by manufacturer

Solution

Replace ECP per the following:

A12-29760-001 to A12-32241-001
A12-29760-002 to A12-32241-002
A12-29760-003 to A12-32241-003
A12-29760-004 to A12-32241-004
A12-29760-005 to A12-32241-005
A12-29760-006 to A12-32241-006

Labels :

49X

Add tags



1 Kudo

Comment