

SS 719-WST 2021 49X Beacon Light Wiring Harness

Applicable Vehicles

49X vehicles

Symptoms

Customer installed beacon lights intermittent operation, flicker, do not flash.

Issue

XMC allows for up to 2amp lights to be used for beacon light installations, some beacon lights in the aftermarket installations are 5amp and greater.

Solution

Revise beacon lights to 2amp outputs.

Labels :

49X

Add tags



0 Kudos

Comment

Powered by

