

CAMPAIGN LAUNCH STATUS

N576 SERVICE ACTION – DEFENDER COOLANT LEVEL SENSOR



CUSTOMER SATISFACTION PROGRAM N576 – COOLANT LEVEL SENSOR LOOSE

AFFECTED MODELS	20-21MY Defender with P6 Engine
VOLUME AFFECTED	6780 USA and 709 Canada
REPAIR	On certain 2020 to 2021 model year Defender vehicles fitted with the P6 engine, a false low coolant level warning message may be displayed on the Instrument Panel Cluster Control Module (IPC), due to a loose coolant level sensor. Affected vehicles with older style parts will require a replacement Coolant Expansion Tank.
REPAIR TIME	0.1hrs to inspect, 0.3hrs to inspect and replace + Drive in/out
CAMPAIGN LAUNCH	Launched October 6 th , 2021
Notes	One unit in retailer inventory. Retailed vehicles to be repaired at next service visit.

