

# TECHNICAL TOPICS

## BODY/CHASSIS



Heatshield Contact With Rear Driveshaft	21 – 22MY Defender
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"><li>- A customer may report a grinding type noise during heavy braking.</li></ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"><li>- This may be caused by the rear driveshaft contacting the exhaust heat shield.</li></ul> <p><u>Status:</u></p> <ul style="list-style-type: none"><li>- Update Prior to Sale Campaign N611 UPS7621 has been published to proactively address this concern on unsold vehicles by providing instructions to modify the exhaust heat shield.</li><li>- TSB JLRNA02090NAS1 has been published to address this concern on sold vehicles upon a customer complaint.</li></ul>	

