# **TECHNICAL TOPICS BODY/CHASSIS**





## Seat Power Fore/Aft Motor Inoperative

#### Customer Voice:

A customer may report that the power seat fore/aft function does not operate.

### Technical Description:

This may be caused by a seat fore/aft motor that has failed.

#### Status:

- The front seat recliner motor has now been released as a lower level repair and the replacement procedures has been added to the TOPIx Workshop Manual.
- Please refer to Workshop Manual > Section 501-10 Seating > Removal and Installation > Front Seat Track Motor.
- The seat back frame no longer needs to be replaced to repair a failed seat track fore/aft motor.
- Part numbers Land Rover = LR154842 & LR154843, Jaguar T2R66084 & T2R66085

12-22MY RR Evoque, 14-22MY RR Sport, 15-22MY Discovery Sport, 17-22MY Discovery, 18-22MY RR Velar, 20-22MY Defender, 17-22MY F-PACE, XF,XE, E-PACE 18-22MY I-PACE









