

Advanced Technical Information

Bulletin #: 2012.1

Part ID: 9025

9

95B Instrument Cluster Pointers Flutter at Startup or "BLF" on Display

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Macan II	2019 - 2020	95B	N/A	N/A

Revision History

Revision	Release Date	Changes	
0	August 10, 2020	Original document	
1	October 27, 2021	Update to include part replacement as a solution	


Condition

There are two related issues that can occur on Macan (95B-II) instrument clusters.

- 1. On startup, after the typical instrument cluster self-test, the tachometer and speedometer pointers flutter or bounce and the led indicator lamps all light up (as shown in figure 1). After a few seconds, behavior returns to normal for the rest of the drive cycle. The issue occurs intermittently.
- 2. BLF is displayed in the lower area of the center dial. (See figure 2.)









Advanced Technical Information

Bulletin #: 2012.1

Part ID: 9025

9

Service Information

Please replace the instrument cluster. All affected parts have been withdrawn by Porsche. The available parts do not have these issues.

Warranty

Please be sure to document your findings in PQIS thoroughly.

Use the following PQIS coding:

Cause location: 90250 Instrument cluster

Cause symptom: 4034 Switching off/on automatically

Search Items

IC, Macan, bounce, needles