

Technical Service Bulletin

Topic	PSIS 750600B0001 Wiring modification for seat belt pre-tensioner buckle switches
Market area	Bentley: worldwide (2WBE)
Brand	Bentley
Transaction No.	2037995/3
Level	EH
Status	Released for publishing

New customer code

Object of complaint	Complaint type	Position
occupant protection, passenger protection -> operation, activation -> belt tensioner trigger	functionality -> operation sequence incorrect	

Vehicle data

Arnage and Silver Seraph

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
0D2BL6	1998	E		Z1J	Z1C	-
0D2BL6	1999	E		Z1J	Z1C	-
3Z22K6	1998	E		Z1H	Z1C	-
3Z22K6	1999	E		Z1H	Z1C	-

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
SCB	***	**	*	*	C	X01001	X01033		
SCB	***	**	*	*	C	X01107	X03050		
SCA	***	**	*	*	C	X01002	X01106		
SCA	***	**	*	*	C	X01078	X03051		
SCA	***	**	*	*	C	H01078	H03051		
SCA	***	**	*	*	C	H01001	H01033		
SCA	***	**	*	*	C	H01107	H03050		
SCA	***	**	*	*	C	H01002	H01106		

Documents

Document name
master.xml
750600b0001_deu.pdf
750600b0001_eng.pdf
750600b0001_esp.pdf
750600b0001_fra.pdf
750600b0001_ita.pdf

Condition

This PSIS has been issued to inform parts and service personnel of a wiring modification to the buckle switches on the seat belt pre-tensioners. If a vehicle enters the workshop with an owner complaint of airbag warning light illumination and codes are stored for;

Drivers seat belt buckle switch resistance undefined – intermittent

Passenger seat belt buckle switch resistance undefined – intermittent

Then the following modification to the wiring should be carried out.

Technical Background

Heritage PSIS (Product Support Information Sheet). Reference attached PDF for details

Production Solution

Reference attached PDF for details

Service

Reference attached PDF for details