



Technical Service Bulletin

Technical Service Bulletin: TSB210191**Released Date: 15-Sep-2021****Coolant Hose Spring Clamps**

Coolant Hose Spring Clamps

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- BES CM0904 EV104B
- BES CM2450 EV105B

Issue

Symptom:

- Coolant leaking from a joint with a spring clamp as a fastener

Root Cause:

- Spring hose clamp **not** properly sealing the joint

Resolution

When there is a coolant leak caused by a weak spring clamp, remove and discard the spring clamp and replace with a worm clamp. See Table 1 below for part number information.

Service Parts Availability

Service parts are available. See Table 1 below for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
One inch worm clamp	-	-	-	5611772
Two inch worm clamp	-	-	-	100432

Document History

Date	Details
2021-8-27	Module Created

Last Modified: 15-Sep-2021
