

QUARANTINE NOTICE

Reference number:	QN-42-1543	Issued: 06 August 2021
Subject:	Incorrect Socket for the Wheel Brace	
Model(s):	DBX	
VIN Range:	Refer to the separately published list of affected Vehicle Identification Numbers (VINs)	
Applicable to:	All Dealers	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Reason for this Quarantine Notice

Aston Martin has discovered some DBX vehicles have an incorrect 21/23mm socket installed on the wheel brace.

Do the workshop procedure that follows to inspect and, if necessary, install the correct 17/19mm socket on the wheel brace.

Workshop Procedure

1. Inspect the size of the socket for the wheel brace.
If a 21/23mm socket is installed go to step 3. (refer to Figure 1).



Figure 1

2. If a 17/19mm socket is installed no further action is necessary.
3. Remove the 21/23mm socket and install the new 17/19mm socket to the wheel brace (refer to Workshop Manual Procedure 42.01.AT).

Warranty Data**Procedure and Labour Time**

Description	Labour Time
Replace the socket for the wheel brace	0.05 hours

Part Data

Description	Part Number	Quantity
Socket 17/19mm	MY83-37-10044	1

If you have any questions related to this document, please refer to the 'Contact Us' link on this webpage, or contact your local Dealer or After Sales Manager.

The English version of this document is written in Simplified Technical English to ASD-STE100™.