

QUARANTINE NOTICE

| | | |
|--------------------------|--|--|
| Reference number: | QN-01-1546 | Issued: 31 August, 2021 |
| Subject: | Install New Screws for the Front Splitter | |
| Model(s): | Vantage F1 Edition | |
| VIN Range: | Refer to the separately published list of affected Vehicle Identification Numbers (VINs) | |
| Applicable to: | All Dealers | |
| Distribute to: | After Sales Manager Executive Manager Service Manager Sales Manager | Warranty Staff Technician(s) Parts Staff |

Reason for this Quarantine Notice

Aston Martin has identified some Vantage F1 edition vehicles that may not have the correct front splitter screws installed. To correct this problem, do the workshop procedure that follows.

Workshop Procedure

1. Lift the vehicle and make it safe.
2. Remove the incorrect screws for the front splitter (refer to Figure 1).
If the screws for the front splitter are not installed go to step 3.




Figure 1

3. Install the correct screws to the front splitter.
4. Lower the vehicle.

Warranty Data**Procedure and Labour Time**

| Description | Labour Time |
|---|-------------|
| Install new screws for the front splitter | 0.10 |

Part Data

| Description | Part Number | Quantity |
|---------------------|-------------------|----------|
| SCREW M6X19 TORX HD | 6G33-FA0115-AB-PK | 1 |

If you have any questions related to this document, please refer to the 'Contact Us' link on this webpage, or contact your local Dealer or After Sales Manager.

The English version of this document is written in Simplified Technical English to ASD-STE100™.