

SERVICE BULLETIN

Reference number:	SB-61-1549	Issued: 24 September, 2021
Subject:	Install New Rear Licence Plate Lamps	
Model(s):	DBX	
Applicable to:	All Dealers	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Reason for this Service Bulletin

Aston Martin has discovered that some vehicles can have unsatisfactory DAB, FM radio and Japanese TV reception when the exterior lamps are set to automatic headlamp mode and activated or dipped beam headlamps are on.

This can be caused by electromagnetic interference from incorrect licence plate lamps installed on some vehicles.

If a customer complains of unsatisfactory DAB, FM radio or Japanese TV reception, do the workshop procedure that follows to install new licence plate lamps.

Workshop Procedure

1. Remove and install new rear licence plate lamps (refer to Workshop Manual Procedure 62.01.FC).

Warranty Data

Procedure and Labour Time

Description	Labour Time	ROT Code
Install new licence plate lamps	0.35 hours	62.01.FC

Part Data

Description	Part Number	Quantity
Licence Plate Lamp	HY53-13550-AB	2

Please Note:

If it is necessary to install new licence plate lamps, send a Warranty Prior Authority Approval form to AM Technical Services. A ww code will be sent to you. Use this code when you order the new part.

If you have any questions related to this document, please refer to the 'Contact Us' link on this webpage, or contact your local Dealer or After Sales Manager.

The English version of this document is written in Simplified Technical English to ASD-STE100™.