

Tech Tip T-TT-0671-21

October 21, 2021

Subject		Market
Roof Rail Gap to Roof		USA
Service Category	Section	
Vehicle Exterior	Exterior Panels/Trim	
Applicability		
2022 Toyota Corolla Cross		

APPLICABLE VEHICLES

2022 Corolla Cross

CONDITION

Some 2022 Corolla Cross vehicles that are equipped with roof rails may exhibit a gapped fitting condition at the inner rear corners between the roof rail protector and the roof panel.



RECOMMENDATIONS

- Currently, there is no confirmed repair for this condition.
- Please do <u>NOT</u> attempt to repair this condition if it is identified.
- CQS strongly encourages the submission of field reports related to this condition to include:
 - Measurement data between roof rail protector and roof panel
 - Ambient air temperature at time condition was identified

LINK REFERENCES

This Tech Tip does not contain any link references