

## **SSM 50250 - 2017 MKZ/Fusion - Battery Drain - Built On Or Before 3-Jun-2016**

Some 2017 MKZ and Fusion vehicles equipped with memory seats and built on or before 03-Jun-2016 may exhibit a discharged battery or a battery drain condition. Before performing normal diagnostics, reprogram the driver door module (DDM) to the latest calibration using the Integrated Diagnostic System (IDS). Use causal part 14B291 and applicable labor operations from Section 10 of the Service Labor Time Standards (SLTS) Manual.

APPLICABLE VEHICLES  
2017 CAR: C9 CD533N MKZ  
2017 CAR: C7 CD391N FUSION