



Volvo Chassis - Correcting The (ABS) MID136 SID 66 FMI 7 Fault Code



> Internal Content

To correct the MID136 SID 66 FMI 7 fault code the latest Bendix VCP file will need to be downloaded.

From TDP (Trucks Dealer Portal) Click on the Uptime Tab - Service - Software Downloads - Bendix VCP, install it on the Tech Tool laptop and then reprogram the ABS ECU.



TRUCKS DEALER PORTAL
UNITED STATES

Trucks	Parts	Uptime	Training	Dealer Admin
Customer Experience > Best Practices & Marketing... > CEM News > Training & Education Recalls		Service > Contacts > Natural Gas Vehicles > Service News > Software Downloads > Tech Support > Tools		Uptime Services > Afterhours Support > ASIST > Certified Uptime Centers > Remote Diagnostics > Volvo Action Service

Software Downloads

Downloads & Links:

[TeamViewer - Remote Connection](#) - allow your retail support agent to connect to your desktop in order to assist you

[Adobe Shockwave](#) - for viewing tests in LMS (learning management system)

[SVG Viewer](#) - to view Scalable Vector Graphics in browsers that do not provide SVG

[RollTek Seat Service Software](#)

[Sun Java Runtime Environment](#) - used for Java applications

[Whip31.exe](#) - whip image viewer

PTT & VCADS Downloads:

[Bendix VCP \(v.3.0.26\) - July 3, 2018](#) ([Click here](#) for VCP Installation Instructions)

[Dearborn Adapter Drivers](#)

[Nexiq Driver Support](#)



Live UI

[ion DLA 2.0](#)

Noregon DLA 2.0 Wireless



Tags

[k88520231](#)

[cummins](#)

[volvo](#)

Related links and attachments

No links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article