

CAMPAIGN LAUNCH STATUS

H380 AND N636 –ENGINE TO BODY GROUND CABLE LOOSE



OWNER NOTIFIED SERVICE ACTION H380 AND N636 – ENGINE TO BODY GROUND CABLE LOOSE

AFFECTED MODELS	21MY F-PACE and Range Rover Velar.
VOLUME AFFECTED	4057 USA 998 CAN
REPAIR	The engine ground cable located on the left side of the engine may be loose. This can lead to a MIL and difficulty starting the engine. The ground fastener is to be inspected and torqued or replaced as required.
REPAIR TIME	0.1hrs plus drive-in/out
CAMPAIGN LAUNCH	October 29 th , 2021
Notes	Unsold vehicles: 94 USA and 43 CANADA. Owners will be notified by mail on or before Nov 12 th .



PRINTED COPIES ARE UNCONTROLLED