

# CAMPAIGN LAUNCH STATUS

## SERVICE ACTIONS H384 & N641 – UNABLE TO COMPLETE SOTA



### OWNER NOTIFIED SERVICE ACTIONS – H384 & N641 – VEHICLES REQUIRE SOFTWARE TO ENABLE SOTA

AFFECTED MODELS	21MY F-PACE, XF, I-PACE E-PACE 20-22MY Defender, RR Velar, Discovery, Discovery Sport, RR Evoque.
VOLUME AFFECTED	630 USA and 110 Canada
REPAIR	Affected vehicles will require software updates to the TCU & ICCM using Pathfinder to enable future SOTA updates and to install the latest PIVI IP31 software
REPAIR TIME	1.6 hrs + Drive in/out
CAMPAIGN LAUNCH	November 8 <sup>th</sup> , 2021
Notes	Owners will be mailed in November.



PRINTED COPIES ARE UNCONTROLLED