

Reference	SSM75618
Models	Defender / L663 Discovery / L462 Discovery Sport / L550 New Range Rover Evoque / L551 Range Rover Velar / L560
Title	Near Field Sensing feature degradation (Surround camera; 360 Park Aid) with PIVI B115E-31 DTC only
Category	Electrical
Last modified	30-Nov-2021 00:00:00
Symptom	204000 Instrumentation

Content**Issue**

Near Field Sensing feature degradation with PIVI B115E-31 DTC only.
Surround camera; 360 Park Aid features or any of the feature is not operating. NFSM DTCs are not logged in confirmed/active status, only PIVI B115E-31 in confirmed status.

Cause

Under investigation

Action

Do NOT replace NFSM for this issue!

Before disturbing any components

Please update PIVI using SOTA & Update NFSM module using Pathfinder, to their respective latest available levels.

Note: NFSM is not on SOTA, PathFinder only

If the issue persists, please raise a TA address to EES_320-NFSM team

anBhdHRicn7MjAyMS0xMj0wMjQxMzoxOT0xNy4wOTIaOzE2NS4yMjUuNTYuMjIwOw==