



STAR ONLINE PUBLICATION



Case Number: S2108000273

Release Date: November 2021

Symptom/Vehicle Issue: DTC B2286-00 Calibration Not Learned - Lost Calibration Set

Discussion: Technician will see DTC DTC B2286-00 Calibration Not Learned/Lost Calibration set by PAM module in active state despite not requiring surround view calibration. A software issue has been identified that may cause the code to reset after a vehicle sleep cycle. Engineering is working on software enhancement that is tentative 1st quarter 2022.

This fault should be ignored unless one of the following cases are true:

- 1) CVPAM was replaced and surround view calibration has not yet been completed.
- 2) customer has complained about surround view image stitching.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found